



CHECKLIST FOR TROUBLESHOOTING PROBLEMS IN PRIVATE SPAS
INSTRUCTIONS FOR CHECKING PROBES

SAT.005.EN
(10122015)

1	Turn off the spa's power supply
2	Turn switch A1 ON
3	Connect spa's power supply
4	Wait until Pr appears on the display and press the power button
5	The temperature of sensor A (SA temperature) and of sensor B (SB temperature) will flash on and off on the display
6	Check that the temperatures of both probes are the same